Amended Attachment 2- Bid Sheet 4/21/2020 Page 1 of 3

Facility: Claude O Markoe			DISTRICT						
Project I.D.	V10203001	IFB NO.	St. Croix (St. Croix (STX)					
	ITEM NO.	DESCRIPTION	QTY	UNITS	UNIT COST	EST COST			
		Buildings Nos. 1,3,4,5,6, and 8							
	226202 226225								

	ITEM NO.	DESCRIPTION	QTY	UNITS	UNIT COST	EST COST
		Buildings Nos. 1,3,4,5,6, and 8				
	226203, 226335,	AA 32 72 0186 47 13 50 50				
	226599, 226731,	Pressure wash and prep all roofs as per silicone membrane product		7-69		
1	226863, 227127	manufactuer's specifictions. See photo detail #1, 2, 3, 4, 6, 14, and 16.	54,000	SF		
	120000000000000000000000000000000000000	Provide adhesion test on various areas of the roofs to determine product's		685		
2	Same as above	adhesive qualities. Apply Prime coat per manufacturer's specifications. Repair areas of roof as	1	LS		
		needed; flash, caulk and reseal all plumbing vents and rainwater drains. Replace				
3	Same as above	rainwater drains where missing.	54,000	SF		
4	Same as above	Apply base and finish coats (2 coats) of liquid silicone membrane	34,000	or .		_
		to achieve 30 mil dry coverage.	54,000	SF		
			5,7,555			
	1	Cafeteria Building No. 1				
		Remove 9 SF area of existing CMU wall and install new 36"x 36" fixed louvered				
		aluminum vent. Install 1/2 PVC line to pressure relief valve to allow water				
		pressure to be released outside. Anchor existing hot water tank to the concrete				
5	226287	floor,	1	L5		
6		Install new 36"x72" aluminum louvered windows	8	EA		
			Þ			
			Allowance		1	
	1	Repair, lubricate, or replace missing, damaged or inoperable window operators	van			
7		at upper East and West Cafeteria wall.	8			
8		Repair or replace damaged Cafeteria ceiling grid/track and tiles in North West	7997			
0		bay to match existing.	40	SF		
_		Building No. 2				_
	226287 (226419 Bldg	Disconnect, relocate and replace generator muffler away from electric service				-
9	2)	drop. (approximately 6'-0").	1	LS		
	parts on the same	Repair, replace and reconstruct chillerbox room roof in accordance with the				
10	226335	Architectural drawings hereto contained in ATTACHMENT 6.	600	SF		
1						
		Building No. 3				
		Check, test, remove and replace all leaking copper pipes with schedule 80 PVC				
122		pipes in Building No. 3- all work must be performed to meet industry standards	1000	10708		
11		and IBC.	400	LF		
_						
_		Building No. 4				
		Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 4- all work must be performed to meet industry standards				
12		and IBC.	300	LF		
			300	LF		
		Building No. 7 - Library / Reading				
		Remove and dispose all contents and damaged interior building components				
Tunios		(including, but not limited to: fixtures, furniture, cabinets, windows, exterior		5		
13	226995	doors, wall sheating, etc.).	1	LS		
0000		Remove, refurbish and reinstall where necessary all existing security bars at				
14		existing windows and exterior doors.	1	LS		
	ı					
		Retain a certified Termite Treatment Specialist to thoroughly inspect, treat and				
		eradicate termites from all building components, including subterreanean				
		eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's				
15		eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty.	1	LS		
15		eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or	1	LS		
	226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to				
15	226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or	3	LS EA		
	226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replae rafters.				
	226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (S) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested				
	226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to				
16		eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of	3	EA		
	226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to				
16		eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replae rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts.	3	EA		
16	226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replae rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 300 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane	3	EA		
16		eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications.	3	EA		
17	226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply	400	SF SF		
16	226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replac rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint.	400	EA SF		
16 17 18	226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replae rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new	3 400 1,325 1,248	SF SF SF		
16 17 18 19	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware.	3 400 1,325 1,248	SF SF SF		
16 17 18	226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles	3 400 1,325 1,248	SF SF SF		
16 17 18 19 20 21	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016"	3 400 1,325 1,248 12 1,248	SF SF SF SF SF		
16 17 18 19	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles	3 400 1,325 1,248	SF SF SF		
16 17 18 19 20 21	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens.	3 400 1,325 1,248 12 1,248	SF SF SF SF SF		
16 17 18 19 20 21	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens.	3 400 1,325 1,248 12 1,248	SF SF SF SF SF		
16 17 18 19 20 21	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replac rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC	3 400 1,325 1,248 12 1,248	SF SF SF SF SF		
16 17 18 19 20 21	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens.	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF SF		
16 17 18 19 20 21 21B	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replae rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Remove and replace all existing vinyl floor tiles Sulding No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8-all work must be performed to meet industry standards	3 400 1,325 1,248 12 1,248	SF SF SF SF SF		
16 17 18 19 20 21 21B	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replae rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Remove and replace all existing vinyl floor tiles Sulding No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8-all work must be performed to meet industry standards	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF SF		
16 17 18 19 20 21 21B	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8- all work must be performed to meet industry standards and IBC.	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF SF		
16 17 18 19 20 21 21B	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8- all work must be performed to meet industry standards and IBC.	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF SF		
16 17 18 19 20 21 21B	226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8- all work must be performed to meet industry standards and IBC. Building No. 10	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF SF		
16 17 18 19 20 21 21B	226995 226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replae rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8- all work must be performed to meet industry standards and IBC. Building No. 10 Remove existing guttering and repair existing wood fascia in kind by: descaling, caulking, priming and applying two (2) coats of exterior latex paint.	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF LF		
16 17 18 19 20 21 21B	226995 226995 226995 226995 226995 227519	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8 - all work must be performed to meet industry standards and IBC. Building No. 10 Remove existing guttering and repair existing wood fascia in kind by: descaling, caulking, priming and applying two (2) coats of exterior latex paint. Pressure wash entire roof to remove all organic buildup and loose corrosion. Apply rust cleaner on all roof and spray on two coats of corrosion resistant	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF LF		
16 17 18 19 20 21 21B	226995 226995 226995 226995 226995	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replac rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8- all work must be performed to meet industry standards and IBC. Building No. 10 Remove existing guttering and repair existing wood fascia in kind by: descalling, caulking, priming and applying two (2) coats of exterior latex paint. Pressure wash entire roof to remove all organic buildup and loose corrosion. Apply rust cleaner on all roof and spray on two coats of corrosion resistant	3 400 1,325 1,248 12 1,248 9	SF SF SF SF SF LF		
16 17 18 19 20 21 21B	226995 226995 226995 226995 226995 227519	eradicate termites from all building components, including subterreanean treatment and provide Owner with applicators and product manufactuer's standard five (5) years warranty. Consult a Structural Engineer on the design for replacement of damaged and or termite infested rafters; secure any required permits and perform work to replace rafters. Remove existing temporary roof tarp and all damaged or termite infested plywood sheathing. Replace damaged plywood with new plywood sheathing to match existing. Install 100 linear feet of new 4" PVC gutters along perimeter of roof and two (2) 3" PVC downspouts. Pressure wash and seal entire roof with two coats of liquid silicone membrane coating per product manufacurer's specifications. Replace damaged interior wall sheathing in kind with treated plywood. Apply two primer coats and one finish coat of paint. Repair and replace all damaged aluminum windows to match existing with new hardware. Remove and replace all existing vinyl floor tiles Fabricate and install nine (9) new 36"x60" window plastic screens. Provide .016" (.406mm) Super Clear Vinyl (Plastic) screens. Building No. 8 Check, test, remove and replace all leaking copper pipes with schedule 80 PVC pipes in Building No. 8 - all work must be performed to meet industry standards and IBC. Building No. 10 Remove existing guttering and repair existing wood fascia in kind by: descaling, caulking, priming and applying two (2) coats of exterior latex paint. Pressure wash entire roof to remove all organic buildup and loose corrosion. Apply rust cleaner on all roof and spray on two coats of corrosion resistant	3 400 1,325 1,248 12 1,248 9	SF SF SF SF LF		

Amended Attachment 2- Bid Sheet 4/21/2020 Page 2 of 3

SCOPE OF WORK AND ITEMIZED BID SHEET

Facility:	Claude O Markoe		DISTRICT		
Project I.D.	V10203001	IFB NO.	St. Croix (STX)		

26						
	227521 (WP addn)	Remove all roof metal panels, guttering and gable trims. Photo Detail No 5, 12 and 13.	F 20-	1922		
27	227647	Examine roof for soft spots in the 3/4 " plywood substrate or defective 2x4	5,000	SF		-
750	(WP addn)	purlins; remove as necessary. Assume that 10% of the purlins are to be changed.				
20			1	LS		
28	227521	Chemically clean all exposed rafters, plywood and fascia; repair where necessary				
		and caulk, prime and apply two coats of exterior acrylic latex to all wood members.				
		monto.	1	LS		
29	227521	Install metal panels to match existing in gauge and and profile. Include ridge and				1
		hip caps, caulking drip edge and closure trims. Provide minimum 24 gauge				l.
		metal.	5,000	SF		-
		Install 6 inch aluminum gutters and 3" pvc leaders. Leaders location to match				
30		existing.	130	LF		
_		Building No. 12 - Gymnasium				
		Pressure wash and prep entire roof area including guttering per project specifications. The building is 20'-0" high, roof is accessible only through				
31	227653	extensive scaffolding or through man-lifts.	10,000	SF		
		Patch, prime and paint all wall surfaces to be repaired. See attached SIKA	10,000			
32	227775	specifications for repair instructions.	1	LS		
	V	Remove ridge caps, repair areas of metal deterioration if required. Tape top and				
	4.00000000	bottom of preformed closure strip before replacing ridge caps. Photo Detail No			1	
33	227653	17	140	LF		
34 35	227653 227653	Apply 1 coats of liquid silicone membrane. Remove and replace gable ends metal closures.	10,000	SF		
33	22/033	Remove vegetation from guttering, clean and install 3" leaders. Photo Detail No.	180	LF	-	-
36	227653	17	1	LS		
37	227698	Repair exterior masonry wall and paint.	8			-
		Remove and legally dispose hurricane damaged gymnasium flooring. Scrape				
38		floor to a smooth finish.	8,038	SF		
39	227653	Clean and sanitize fixtures, floors and walls.	1	LS		
		Remove damaged exterior 6' x 7' metal double doors and existing hardware.				
		Match and replace in kind with new 6' x 7' double exterior doors including				
		commercial grade hardware including door lock sets, hinges, door closure arms,				
40		panic release bars and thresholds. Replace hardware at four (4) other exiting exterior doors.				1
40		Cut out and dispose all damaged roof insulation including insulation blown in	4	EA		
41	227653	and around the gymnasium.	1,000	SF		
	22.000	Install new 6" thick (pre-engineered steel building) R19 vinyl faced roof	1,000	3F		
42	227653	insulation.	1,000	SF		
43	227653	Repair damaged weather head and service entrance.	1	LS		
	58835855					
44	227653	Remove and replace damaged roof ventilator fans to match existing.	2	EA		
45	227653	Water proof and seal fan openings with approved silicone (elastomeric) based roof coating in accordance with manufactuer's recommendation.				
46			4	EA		4
			200			
47	227653	Remove and replace damaged downspouts in-kind.	300	LF		
47		Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind.	300 400	LF LF		
47 48	227653	Remove and replace damaged downspouts in-kind.	400	LF		
	227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance				
48	227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance	400	LF		
	227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered	400	LF		
48	227653 227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed	400	LF		
48	227653 227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original	400	LF		
48	227653 227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized	400	LF		
48	227653 227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos	200	LF SF		
48	227653 227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21.	400	LF		
49	227653 227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders	200	LF SF		
49	227653 227653 227653 227653	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21.	200	LF SF		
49	227653 227653 227653 227653 227907	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws	200	LF SF		
49 50 51	227653 227653 227653 227653 227907 227915	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5.	200	LF SF		
48 49 50 51 52	227653 227653 227653 227653 227907 227907	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane.	1 1 130	LF SF		
48 49 50 51 52	227653 227653 227653 227653 227907 227915	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT S. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and	1 130 4,500	LF SF		
48 49 50 51 52	227653 227653 227653 227653 227907 227907	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and	1 130 4,500	LF SF		
48	227653 227653 227653 227653 227907 227907	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT S. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and	1 130 4,500 4,500	LS LS LF SF		
48 49 50 51 52 53	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim.	1 130 4,500	LF SF		
48 49 50 51 52 53	227653 227653 227653 227653 227907 227907	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT S. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim.	1 130 4,500 4,500	LS LS LF SF		
48 49 50 51 52 53	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim.	1 130 4,500 4,500	LF SF LS LF SF SF		
48 49 50 51 52 53	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever.	1 130 4,500 4,500	LS LS LF SF		
48 49 50 51 52 53	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever.	1 130 4,500 4,500 140	LF SF LS LF SF SF SF		
48 49 50 51 52	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms.	1 130 4,500 4,500	LF SF LS LF SF SF		
48 49 50 51 52 53 54	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever.	1 130 4,500 4,500 140 2,340 2,700	LF SF LF SF SF SF SF		
48 49 50 51 52 53 54	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and	1 130 4,500 4,500 140	LF SF LS LF SF SF SF		
48 49 50 51 52 53 55 56 57 58	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and floors. Replace and install 6mil plastic window screens. Chip and patch damaged wall around windows in room 601.	1 130 4,500 4,500 140 2,340 2,700	LF SF LF SF SF SF SF		
48 49 50 51 52 53 55 56 57 58	227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and floors. Replace and install 6mil plastic window screens. Chip and patch damaged wall around windows in room 601. Remove and replace hurricane damaged acoustic ceiling tile grid and tiles in	1 130 4,500 4,500 140 2,340 2,700 2,700	LF SF LF SF SF LF SF SF LF SF SF LS		
49 50 51 52 53 54 55 56 57 58 59	227653 227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and floors. Replace and install 6mil plastic window screens. Chip and patch damaged wall around windows in room 601.	1 130 4,500 4,500 140 2,340 2,700 2,700	LF SF LF SF SF LF SF SF LF SF SF LS		
48 49 50 51 52 53 54 55 56	227653 227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and floors. Replace and install 6mil plastic window screens. Chip and patch damaged wall around windows in room 601. Remove and replace hurricane damaged acoustic ceiling tile grid and tiles in	1 130 4,500 4,500 140 2,340 2,700 1 3	LF SF LF SF SF SF SF SF SF SF		
49 50 51 52 53 54 55 56 57 58 59 60	227653 227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT S. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and floors. Chip and patch damaged wall around windows in room 601. Remove and replace hurricane damaged acoustic ceiling tile grid and tiles in room 604.	1 130 4,500 4,500 140 2,340 2,700 1 3	LF SF LF SF SF SF SF SF SF SF		
49 50 51 52 53 54 55 56 57 58 59	227653 227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT 5. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and floors. Replace and install 6mil plastic window screens. Chip and patch damaged wall around windows in room 601. Remove and replace hurricane damaged acoustic ceiling tile grid and tiles in room 604. Replace damaged acoustic ceiling tiles in rooms 601, 602 and Storerooms.	1 130 4,500 4,500 4,500 140 2,340 2,700 1 3	LF SF LF SF SF SF SF SF SF SF		
48 49 50 51 52 53 55 55 56 57 58 59	227653 227653 227653 227653 227653 227907 227907 227915 227785 227785 227785 227785 227785 227785 227785 227785	Remove and replace damaged downspouts in-kind. Remove and replace damaged gutters in-kind. Patch all roof penetrations with Silicone (elastomeric) roof coating in accordance with manufacturer's recommendation. Building Number No. 13 Shore-up existing metal shed roof to remove 4 structurally impaired cantilevered beams along with all purlins that cannot be repaired. Replace all removed members and restore shed sections so that they can perform their original function. Any purlins to be replaced shall be with hot-dipped galvanized members. Consult structural engineer on replacement design. Photo Detail Nos 20 and 21. Install 12 inch metal closure plate, 6 inch guttering and two 3" pvc leaders connected to the existing Photo Detail No 10 Pressure wash and prep entire roof. Remove lifted, corroded or damaged screws and repair areas of corrosion. See Specifications in ATTACHMENT S. Apply 1 coat of liquid silicone membrane. Remove ridge caps, repair areas of metal deterioration if required. Tape top and bottom of preformed closure strip before placing ridge caps and remove and replace gable trim. Apply primer plus two (2) coats of paint to the south face of building No 13. and the newly repaired underside of the cantilever. Remove and dispose all interior damaged fixtures, furniture, cabinets and debris in classrooms, restroom and storerooms. Clean and sanitize all classrooms, restrooms and storerooms including walls and floors. Chip and patch damaged wall around windows in room 601. Remove and replace hurricane damaged acoustic ceiling tile grid and tiles in room 604.	1 130 4,500 4,500 4,500 140 2,340 2,700 1 3	LF SF LF SF SF SF SF SF SF SF		

Amended Attachment 2- Bid Sheet 4/21/2020 Page 3 of 3

SCOPE OF WORK AND ITEMIZED BID SHEET

Facility:	Claude O Markoe		DISTRICT			
Project I.D.	V10203001	IFB NO.	St. Croix (STX)		
					and the same of th	
		North Fence and Gate Repair				
62		Clean, cut, weed, remove and dispose all bush, grass, and shrubbery from North of Property Line- Fence.	300	LF		
63		North fence line- Repair damaged or toppled fencing to include the installation of post where required, treated wood bracing to hold toppled "intact" fencing and the installation of fencing where missing or damaged beyond use.	700	LF		
64		Repair damaged North/West gate.	1	LS		1
65		Project clean-up and close out.	1	LS		1
		Subtotal				
66		General Conditions and Requirement 15%:				
		BID LUMP-SUM TOTAL:				
for submittin	ng a TOTAL LUMP SUN	ed in the U.S. Virgin Islands construction market; and also to ensure that all Contract COST for the complete construction of the project. OR THIS INVITATION FOR BID, IS LISTED AS WRITTEN IN U.S. CURRENCY IN WORDS I				
USD-						
030-						
Vendor's Sig		Date	1			
Company Na	ame/Mailing Address	Telephone:				
			1			

The undersigned vendor, service provider, contractor hereby certifies that he/she has thoroughly examined the entire Scope Of Work, visited the project site(s) and familiarized himself/herself with all conditions, and hereby proposes to furnish all labor, tools, materials, equipment, services and transportation associated therewith. All work and services provided herein shall conform in all respects to all Project Plans, Specifications, written Scopes Of Work and applicable local, federal, construction trade, and/or Manufacturer's Product Specifications; equipment current applicable codes, standards and procedures. The vendor, service provider, contractor, pledges to complete all work herein within ONE HUNDRED TWENTY (120) CALENDAR DAYS.